


Exterior ceiling perimeter / wall transition

What remains free to move behind the finished trim?



Architectural concept. Appearance does not establish geometry, compatibility or code compliance.



WD-CL-PERIMETER-001 / RELATIONSHIP STUDY

Dimensionless component envelopes. Exact profile and hardware geometry remain unresolved.

Assembly and verification

Choose an exposed termination or a cover-trim appearance only after identifying board movement, finish sequence and fastening access. Keep services and penetrations outside this perimeter study.

Profile / supplied material

Actual ceiling and trim sections required. No universal trim overlap or perimeter gap is assigned.

Review sequence

1. Boundary

Record the adjacent wall finish.

2. Support

Resolve the end support and concealed attachment.

3. Movement

Document the required perimeter allowance.

4. Finish

Review trim or exposed-edge treatment.

Required project evidence

- ☐ Board-end support
- ☐ Required movement clearance
- ☐ Trim fastening and access
- ☐ Wall finish and installation sequence

Source record

Verification state: conceptual coordination study. Source relationships are cited below; supplied-product fit and fabrication geometry are not verified.

US Forest Service Â/ moisture relations

Wood moisture and movement background; not a fastener, span or profile approval.

<https://research.fs.usda.gov/treesearch/62243>

Hardwood Profiles Â/ supplied geometry registry

Resolve the exact supplied profile and production drawing. Unresolved cuts remain unresolved.

<https://hardwoodprofiles.com/profile-explorer>

Canonical detail

<https://wooddetails.com/details/ceiling-perimeter-wall-transition>

Limitations

This study explains coordination questions. It is not a dimensioned construction drawing, installation specification, structural design, waterproofing instruction or product approval. Use current manufacturer instructions, approved production drawings and the project design. Generated architectural context is illustrative. No DWG or DXF is supplied because verified distribution-ready CAD is not available for this study.